

Linux Interface Specification Yocto recipe

Release Note: Software

R-Car H3/M3 Series

All information contained in these materials, including products and product specifications, represents information on the product at the time of publication and is subject to change by Renesas Electronics Corp. without notice. Please review the latest information published by Renesas Electronics Corp. through various means, including the Renesas Electronics Corp. website (http://www.renesas.com).

Notice

- 1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation or any other use of the circuits, software, and information in the design of your product or system. Renesas Electronics disclaims any and all liability for any losses and damages incurred by you or third parties arising from the use of these circuits, software, or information.
- 2. Renesas Electronics hereby expressly disclaims any warranties against and liability for infringement or any other disputes involving patents, copyrights, or other intellectual property rights of third parties, by or arising from the use of Renesas Electronics products or technical information described in this document, including but not limited to, the product data, drawing, chart, program, algorithm, application examples.
- 3. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
- 4. You shall not alter, modify, copy, or otherwise misappropriate any Renesas Electronics product, whether in whole or in part. Renesas Electronics disclaims any and all liability for any losses or damages incurred by you or third parties arising from such alteration, modification, copy or otherwise misappropriation of Renesas Electronics products.
- 5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The intended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.
 - "Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; and industrial robots etc.
 - "High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control (traffic lights); large-scale communication equipment; key financial terminal systems; safety control equipment; etc.
 - Renesas Electronics products are neither intended nor authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems, surgical implantations etc.), or may cause serious property damages (space and undersea repeaters; nuclear power control systems; aircraft control systems; key plant systems; military equipment; etc.). Renesas Electronics disclaims any and all liability for any damages or losses incurred by you or third parties arising from the use of any Renesas Electronics product for which the product is not intended by Renesas Electronics.
- 6. When using the Renesas Electronics products, refer to the latest product information (data sheets, user's manuals, application notes, "General Notes for Handling and Using Semiconductor Devices" in the reliability handbook, etc.), and ensure that usage conditions are within the ranges specified by Renesas Electronics with respect to maximum ratings, operating power supply voltage range, heat radiation characteristics, installation, etc. Renesas Electronics disclaims any and all liability for any malfunctions or failure or accident arising out of the use of Renesas Electronics products beyond such specified ranges.
- 7. Although Renesas Electronics endeavors to improve the quality and reliability of Renesas Electronics products, semiconductor products have specific characteristics such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Further, Renesas Electronics products are not subject to radiation resistance design. Please ensure to implement safety measures to guard them against the possibility of bodily injury, injury or damage caused by fire, and social damage in the event of failure or malfunction of Renesas Electronics products, such as safety design for hardware and software including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures by your own responsibility as warranty for your products/system. Because the evaluation of microcomputer software alone is very difficult and not practical, please evaluate the safety of the final products or systems manufactured by you.
- 8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. Please investigate applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive carefully and sufficiently and use Renesas Electronics products in compliance with all these applicable laws and regulations. Renesas Electronics disclaims any and all liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
- 9. Renesas Electronics products and technologies shall not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You shall not use Renesas Electronics products or technologies for (1) any purpose relating to the development, design, manufacture, use, stockpiling, etc., of weapons of mass destruction, such as nuclear weapons, chemical weapons, or biological weapons, or missiles (including unmanned aerial vehicles (UAVs)) for delivering such weapons, (2) any purpose relating to the development, design, manufacture, or use of conventional weapons, or (3) any other purpose of disturbing international peace and security, and you shall not sell, export, lease, transfer, or release Renesas Electronics products or technologies to any third party whether directly or indirectly with knowledge or reason to know that the third party or any other party will engage in the activities described above. When exporting, selling, transferring, etc., Renesas Electronics products or technologies, you shall comply with any applicable export control laws and regulations promulgated and administered by the governments of the countries asserting jurisdiction over the parties or transactions.
- 10. Please acknowledge and agree that you shall bear all the losses and damages which are incurred from the misuse or violation of the terms and conditions described in this document, including this notice, and hold Renesas Electronics harmless, if such misuse or violation results from your resale or making Renesas Electronics products available any third party.
- 11. This document shall not be reprinted, reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
- 12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products.
- (Note 1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its majority-owned subsidiaries.
- (Note 2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

Trademark

- · Linux® is the registered trademark of Linus Torvalds in the U.S. and other countries.
- ARM is a registered trademark of ARM Limited (or its subsidiaries) in the EU and/or elsewhere. All rights reserved.
- Windows and Windows Media are registered trademarks of Microsoft Corporation in the United States and other countries.
- · Other company names and product names mentioned herein are registered trademarks or trademarks of their respective owners.
- Registered trademark and trademark symbols (\circledR and \intercal M) are omitted in this document

How to Use This Manual

• [Readers]

This manual is intended for engineers who develop products which use the R-Car H3/M3 processor.

• [Purpose]

This manual is intended to give users an understanding of the functions of the R-Car H3/M3 processor device driver and to serve as a reference for developing hardware and software for systems that use this driver.

• [How to Read This Manual]

It is assumed that the readers of this manual have general knowledge in the fields of electrical

- engineering, logic circuits, microcontrollers, and Linux.
 - → Read this manual in the order of the CONTENTS.
- To understand the functions of a multimedia processor for R-Car H3/M3
 - → See the R-Car H3/M3 User's Manual.
- To know the electrical specifications of the multimedia processor for R-Car H3/M3
 - → See the R-Car H3/M3 Data Sheet.

• [Conventions]

The following symbols are used in this manual.

Data significance: Higher digits on the left and lower digits on the right

Note: Footnote for item marked with Note in the text **Caution**: Information requiring particular attention

Remark: Supplementary information

Numeric representation: Binary ... ××××, 0b××××, or ××××B

Decimal ... ××××

Hexadecimal ... $0x \times \times \times$ or $\times \times \times \times H$ Data type: Double word ... 64 bits

Word ... 32 bits Half word ... 16 bits

Byte ... 8 bits

Table of Contents

2.1	ist of R-Car H3/M3 Series Linux Yocto package contents	
2.2	English documentation	2
2.3	Japanese documentation	
3. No	otice	3
4. Cł	hange History	4
4.1	v2.0.0	4
4.2	v2.1.0	4
4.3	v2.2.0	4
4.4	v2.3.0	4
4.5	v2.4.0	5
4.6	v2.5.2	5
4.7	v2.6.0	5
4.8	v2.7.0	6
4.9	v2.8.0	6
4.10	v2.9.0	7
4.11	v2.10.0	7
4.12	v2.11.0	7
4.13	v2.12.0	8
4.14	v2.15.0	8
4.15	v2.16.0	9
4.16	v2.17.0	9
4.17	v2.19.0	
4.18	v2.21.0	
4.19	v2.23.0	11
~ F	· · · · · · · · · · · · · · · · · · ·	1.0
	evision Numbers of Referred S/W Packages	
o. Co	ommit ID of Renesas Yocto Recipe	



1. Introduction

This manual explains the package construction of R-Car H3/M3 Linux Yocto package.

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe Series Linux Yocto package contents

2. List of R-Car H3/M3

2. List of R-Car H3/M3 Series Linux Yocto package contents

The followings are included in this product.

2.1 Software

IPL, U-Boot, Kernel, root file system and Multi Media packages are provided by using the Yocto Project.

2.2 English documentation

NO.	Contents	File name	version
1	Start-Up guide	RENESAS_RCH3M3_YoctoStartupGuide_UME_v2.23.0.pdf	2.23.0

2.3 Japanese documentation

None.

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe

3. Notice

3. Notice

- In BSP only, local-wayland.conf is provided. However, it is not supported.
- System settings (CPU clock, DDR clock, etc): Please refer to IPL Release note.

4. Change History

4.1 v2.0.0

- Initial Revision of the R-Car H3 Linux BSP package by Yocto Recipe Package based on Yocto Project 1.8.
 Yocto recipe package v2.0.0 for R-Car H3.
 - o R-Car H3 Linux BSP package based on Linux Kernel 4.2-RC7.
 - o 3D Graphics package
 - GSX: Pre-Alpha (64bit only)
- Not support lib32-core-image-weston.

4.2 v2.1.0

- Yocto recipe package v2.1.0 for R-Car H3.
 - o R-Car H3 Linux BSP package v3.0.0 based on Linux Kernel 4.2.
 - Please refer BSP's release note in detail
 - o U-Boot: The file name was changed into u-boot-elf.srec from u-boot.srec.
- Not support 3D graphics and Multi Media Packages.
- Recipe of IPL cannot create the following file. Please contact a Renesas Electronics sales office.
 - o bootparam sa0.srec
 - o cert header sa6.srec
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.

4.3 v2.2.0

- Yocto recipe package v2.2.0 for R-Car H3.
 - o R-Car H3 Linux BSP package v3.0.2 based on Linux Kernel 4.2.
 - Please refer BSP's release note in detail
- Recipe of IPL can create all srec file.
 - Add recipe for bootparam sa0.srec
 - Add recipe for cert header sa6.srec
- Support 3D graphics and Multi Media Packages
 - o Please refer to Section5 table1 for package name and version.
 - Please add mem=2048M to bootargs.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes and Audio function doesn't work that are caused by un-optimized QoS settings.

4.4 v2.3.0

- Yocto recipe package v2.3.0 for R-Car H3.
 - o R-Car H3 Linux BSP package v3.0.3 based on Linux Kernel 4.2.
 - Please refer BSP's release note in detail
 - o Updated QoS settings. Audio function works.

- Please refer IPL's release note in detail
- o Fix symbol error in gdb. This is defect of yoctoproject (poky) gdb recipes.
- 3D graphics and Multi Media Packages
 - o Same as v2.2.0
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.

4.5 v2.4.0

- Yocto recipe package v2.4.0 for R-Car H3.
 - R-Car H3 Linux BSP package
 - Same as v2.3.0
 - o Updated IPL
 - arm-trusted-firmware adds the supports of PSCI function.
 - Please refer to IPL's release note
 - O Userland: Add media-ctl (v4l-utils) package
- 3D graphics and Multi Media Packages
 - o Same as v2.2.0
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.

4.6 v2.5.2

- Yocto recipe package v2.5.2 for R-Car H3.
 - Yocto Recipes package base upgrade to Yocto Project 2.0 from 1.8
 - linaro gcc version upgrade to 5.1 from 4.9
 - Changed XDG RUNTIME DIR to /run/usr/root from /run/user/0
 - R-Car H3 Linux BSP package
 - Same as v2.4.0
 - o Updated IPL for linaro gcc 5.1
- 3D graphics Packages and Multi Media Packages
 - o Upgrade linaro gcc version to 5.1 from 4.9 (except omx video)
 - o mem=2048M in bootargs became unnecessary
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.
- In MMP, please always enable H.264 decoder. Default is enable.

4.7 v2.6.0

- Yocto recipe package v2.6.0 for R-Car H3.
 - o Wayland/Weston upgrade to 1.8 from 1.6
 - o Add Security softwares to userland in BSP only (core-image-minimal)

- o R-Car H3 Linux BSP package v3.1.1 based on Linux Kernel 4.4
 - Upgrade linux kernel version to v4.4 rc2 from v4.2
 - Deleted console setting from bootargs
 - Please refer BSP's release note in detail
- Updated IPL for Linux Kernel 4.4
 - Please refer to IPL's release note
- 3D graphics Packages and Multi Media Packages
 - o OMX Video: upgrade linaro gcc version to 5.1 from 4.9
 - o GFX: support Wayland/Weston 1.8
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.
- In MMP, please always enable H.264 decoder. Default is enable.

4.8 v2.7.0

- Yocto recipe package v2.7.0 for R-Car H3.
 - o Wayland/Weston upgrade to 1.9 from 1.8
 - o Add support R-Car H3 Ver.1.1
 - o R-Car H3 Linux BSP package v3.2.0 based on Linux Kernel 4.4
 - Upgrade linux kernel version to v4.4 from v4.4 rc2
 - Please refer BSP's release note in detail
 - Updated IPL for Linux Kernel 4.4
 - Add support secure boot in optee-os
 - Add support 32bit TEE Client Library
 - Please refer to IPL's release note
- 3D graphics Packages and Multi Media Packages
 - o GFX: Support Wayland/Weston 1.9
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.
- In MMP, please always enable H.264 decoder. Default is enable.

4.9 v2.8.0

- Yocto recipe package v2.8.0 for R-Car H3/M3.
 - o Add support R-Car M3.
 - o R-Car H3/M3 Linux BSP package v3.2.1 based on Linux Kernel 4.4
 - Please refer BSP's release note in detail
 - o Updated IPL for Linux Kernel 4.4
 - Please refer to IPL's release note
- 3D graphics Packages and Multi Media Packages
 - o GFX: support R-Car M3
 - o MMP: alpha2 release (Only R-Car H3)
 - Add support Lossy compression (Frame Compression Near Lossless, FCNL) feature. For this feature, includes IPL support and Linux Kernel support.

- R-Car M3 is not support Multi Media Package.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.

4.10 v2.9.0

- Yocto recipe package v2.9.0 for R-Car H3/M3.
 - R-Car H3/M3 Linux BSP package v3.2.2 based on Linux Kernel 4.4
 - Please refer BSP's release note in detail
 - Updated IPL for Linux Kernel 4.4
 - Please refer to IPL's release note
- 3D graphics Packages and Multi Media Packages
 - R-Car M3 supported Multi Media Packages
 - MMP: Alpha2 release
 - Ether AVB: Integrated in vocto recipe package
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.
- R-Car M3 does not support Lossy compression.
- In R-Car M3, if vspm, v4l2 or vspfilter are used, please use up-down scaling except for x1 in them.

4.11 v2.10.0

- Yocto recipe package v2.10.0 for R-Car H3/M3.
 - linaro gcc version upgrade to 5.2 from 5.1
 - R-Car H3/M3 Linux BSP package v3.3.0 rc3 based on Linux Kernel 4.6
 - Upgrade linux kernel version to v4.6 from v4.4
 - Please refer BSP's release note in detail
 - Updated IPL for Linux Kernel 4.6
 - Lossy compression is enabled only MMP configuration
 - Please refer to IPL's release note
- 3D graphics Packages and Multi Media Packages
 - Audio, Video, GFX: upgrade linaro gcc version to 5.2 from 5.1
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- 32-bit Environment included in SDK cannot be used. Please build 32bit SDK (lib32-core-image-weston-sdk).
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.

4.12 v2.11.0

- Yocto recipe package v2.11.0 for R-Car H3/M3.
 - Changed ARM gcc option to -mtune=cortex-a57.cortexa53
 - Userland supports only 64bit. 32bit environment was deleted.
 - R-Car H3/M3 Linux BSP package v3.3.1 rc4 based on Linux Kernel 4.6
 - Please refer BSP's release note in detail

4. Change History

- 3D graphics Packages and Multi Media Packages
 - o Audio: Added ALAC, FLAC, Dolby(R) Digital decoder and AAC-LC encoder
 - Video: Added DivX and RealVideo decoder
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Display may have a distorted screen in sometimes caused by un-optimized QoS settings.
- In MMP configuration, fixed the following issue.

Data corruption occurs when kernel reads any data that is stored in "CMA for Lossy comp" (default: $0x00_5400_0000 - 0x00_5700_0000$) because of "reusable" memory property in DeviceTree.

4.13 v2.12.0

- Yocto recipe package v2.12.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.3.2 based on Linux Kernel 4.6
 - Please refer BSP's release note in detail
- 3D graphics Packages and Multi Media Packages
 - o MMP: Beta release
 - CMS: CMM3 and VSP2 Basic Color Management is integrated by one package.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP TRG signal for Suspend to RAM.
- You have to re-compile out-of-recipe software like user application by v2.12.0 SDK toolchains.

4.14 v2.15.0

- Yocto recipe package v2.15.0 for R-Car H3/M3.
 - Yocto Recipes package base upgraded to Yocto Project 2.1.2 from 2.0
 - o R-Car H3/M3 Linux BSP package v3.4.0 based on Linux Kernel 4.9
 - Upgrade Linux kernel version to v4.9 from v4.6
 - Fix frame work of System Suspend to RAM
 - Please refer BSP's release note in detail
 - o U-Boot: Changed load address to 0x50000000 from 0x49000000
 - Updated IPL for Linux Kernel 4.9
 - IPL: Clean-up to the DDR setting code
 - IPL: Add support R-Car Series, 3rd Generation M3 Ver.1.0
 - Please refer to IPL's release note
 - o Wayland/Weston upgraded to 1.11 from 1.9.
 - o Gstreamer upgraded to v1.6.3 from v1.4.5
 - Gstreamer-1.0-plugins-bad: Support Wayland/Weston 1.11.0
- 3D graphics Packages and Multi Media Packages
 - o GFX: Support Wayland/Weston 1.11.0.
 - o ADSP, Video: Fix duplicate header files
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP_TRG signal for Suspend to RAM.
- The dtb filename was changed in R-Car H3. Only "Image-r8a7795-es1-salvator-x.dtb" is supported in this version. Please use "Image-r8a7795-es1-salvator-x.dtb". It supports R-Car H3 Ver.1.0 and Ver.1.1.
- You have to re-compile out-of-recipe software like user application by v2.15.0 SDK toolchains.

4.15 v2.16.0

- Yocto recipe package v2.16.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.5.1 based on Linux Kernel 4.9 Stable
 - Upgrade Linux kernel version to v4.9 Stable from v4.9 RC1
 - Please refer BSP's release note in detail
 - o Updated IPL for Linux Kernel 4.9 Stable
 - Please refer to IPL's release note
- · 3D graphics Packages and Multi Media Packages
 - o GFX: Update to support Linux Kernel 4.9 Stable
 - Wayland: Update libgbm to v10. 3.0
 - o XDG RUNTIME DIR has been changed from "/run/user/root" to "/run/user/0".
 - o Video: Update video packages to v3.0.7
 - Support new codecs: H263 Decode
 - Change location of include directory, which stores common user header files, to \$(INCSHARED).
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP TRG signal for Suspend to RAM.
- The dtb filename was changed in R-Car H3. Only "Image-r8a7795-es1-salvator-x.dtb" is supported in this version. Please use "Image-r8a7795-es1-salvator-x.dtb". It supports R-Car H3 Ver.1.0 and Ver.1.1.
- Please update your local.conf and bblayers.conf corresponding to Yocto v2.16.0 package. You can refer to meta-reargen3/docs/sample/conf/ for updated contents.
- You have to re-compile out-of-recipe software like user application by v2.16.0 SDK toolchains.
- In some boards, the resuming from System Suspend to RAM may cause unstable operation or failed to resume.
- v2.15.0 or later: U-Boot start address is 0x50000000

4.16 v2.17.0

- Yocto recipe package v2.17.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.5.2 based on Linux Kernel 4.9 Stable.
 - Please refer BSP's release note in detail.
 - o Updated IPL version according to BSP v3.5.2.
 - Please refer to IPL's release note.
- 3D graphics Packages and Multi Media Packages
 - o GFX: Update firmware to support both Ver.1.x and Ver.2.0.
 - Wayland: Support ivi-shell config for weston.ini.
 - To add config for ivi-shell, please enable DISTRO_FEATURES_append = "ivi-shell" in local.conf.
 - o Video: Update video packages to v3.0.8.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP TRG signal for Suspend to RAM.
- The dtb filename was changed in R-Car H3.
 - o Please use "Image-r8a7795-es1-salvator-x.dtb". It supports R-Car H3 Ver.1.0 and Ver.1.1.
 - o Please use "Image-r8a7795-salvator-x.dtb". It supports R-Car H3 Ver.2.0.
 - o Please use "Image-r8a7795-salvator-xs.dtb". It supports R-Car H3 Ver.2.0 (RTP0RC7795SIPB0012S).

- Please update your local.conf and bblayers.conf corresponding to Yocto v2.17.0 package. You can refer to meta-rear-gen3/docs/sample/conf/ for updated contents.
- You have to re-compile out-of-recipe software like user application by v2.17.0 SDK toolchains.
- In some boards, the resuming from System Suspend to RAM may cause unstable operation or failed to resume.
- v2.17.0 or later:
 - U-Boot start address is 0x50000000.
 - o BL2 start address is 0xE6304000.

4.17 v2.19.0

- Yocto recipe package v2.19.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.5.3 based on Linux Kernel 4.9 Stable.
 - Add support R-Car M3 Ver.1.1 (RTP0RC7795SIPB0012S).
 - Please refer BSP's release note in detail.
 - Updated IPL version according to BSP v3.5.3.
 - Please refer to IPL's release note.
- 3D graphics Packages and Multi Media Packages
 - o GFX: Change name of graphics initscript.
 - Video: Update video packages to v3.0.9.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP_TRG signal for Suspend to RAM.
- The dtb filename was changed in R-Car H3.
 - o Please use "Image-r8a7795-es1-salvator-x.dtb". It supports R-Car H3 Ver.1.0 and Ver.1.1.
 - o Please use "Image-r8a7795-salvator-x.dtb". It supports R-Car H3 Ver.2.0.
 - o Please use "Image-r8a7795-salvator-xs.dtb". It supports R-Car H3 Ver.2.0 (RTP0RC7795SIPB0012S).
- The dtb filename was changed in R-Car M3.
 - o Please use "Image-r8a7796-salvator-x.dtb". It supports R-Car M3 Ver.1.0 and Ver.1.1.
 - Please use "Image-r8a7796-salvator-xs.dtb". It supports R-Car M3 Ver.1.0 and Ver.1.1 (RTP0RC7795SIPB0012S).
- You have to re-compile out-of-recipe software like user application by v2.19.0 SDK toolchains.
- In some boards, the resuming from System Suspend to RAM may cause unstable operation or failed to resume.
- v2.17.0 or later:
 - U-Boot start address is 0x50000000.
 - o BL2 start address is 0xE6304000.

4.18 v2.21.0

- Yocto recipe package v2.21.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.5.5 based on Linux Kernel 4.9 Stable.
 - Please refer BSP's release note in detail.
 - Updated IPL version according to BSP v3.5.5.
 - Please refer to IPL's release note.
- 3D graphics Packages and Multi Media Packages
 - o GFX: Update to support Linux Kernel 4.9 Stable.

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe

- Change History
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP TRG signal for Suspend to RAM.
- You have to re-compile out-of-recipe software like user application by v2.21.0 SDK toolchains.
- In some boards, the resuming from System Suspend to RAM may cause unstable operation.
- v2.17.0 or later:
 - U-Boot start address is 0x50000000.
 - o BL2 start address is 0xE6304000.

4.19 v2.23.0

- Yocto recipe package v2.23.0 for R-Car H3/M3.
 - o R-Car H3/M3 Linux BSP package v3.5.8 based on Linux Kernel 4.9 Stable.
 - Please refer BSP's release note in detail.
 - Updated IPL version according to BSP v3.5.8.
 - Please refer to IPL's release note.
- 3D graphics Packages and Multi Media Packages
 - o GFX: Update to support Linux Kernel 4.9 Stable.
 - o GFX: Create GFX packagegroup to maintain GFX pkgs easier.
 - Video: Update video packages to v3.0.10.
 - Use \${RENESAS DATADIR} variable for /usr/local directory instead of hard coding.
 - Add libegl recipe which provides build dependency on virtual/egl.
 - Need to set value for PREFERRED_PROVIDER_virtual/egl in local.conf from gles-user-module to libegl into local.conf.
 - o Add .gitignore for *tar.bz2 and *.tar.gz packages.
- In BSP Only, core-image-weston is not supported even though local-wayland.conf is provided.
- Please set SW7 Pin-1. In after Yocto BSP v2.12.0, it is necessary to enable BKUP_TRG signal for Suspend to RAM.
- You have to re-compile out-of-recipe software like user application by v2.23.0 SDK toolchains.
- v2.17.0 or later:
 - o U-Boot start address is 0x50000000.
 - o BL2 start address is 0xE6304000.

5. Revision Numbers of Referred S/W Packages

Table 1: Revision Numbers of Referred S/W Packages

Package Name (abbreviation)	Package Name	Package Id	Package Revision	
U-Boot On Board Drivers On chip Peripheral Drivers	R-Car H3/M3 Linux BSP	_	v3.5.8	
etc.				
Initial Program Loader	R-Car H3/M3/E3 Initial Program Loader	_	_	
OpenGL3.1 Library	R8A7795 GX6650 OpenGL ES3.1 Library for Linux	RTM0RC7795GLTG0001SL40C	1.3.4	
GSX driver	R8A7795 GX6650 Device Driver for Linux	RCH3G001L4001ZDO	1.3.4	
GSX Offline Compiler	R8A7795 GX6650 GLSL Offline Compiler for Linux	RCH3G002L4001ZNI	1.3.4	
OpenGL3.1 Library	R8A7796 GX6250 OpenGL ES3.1 Library for Linux	RTM0RC7796GLTG0001SL40C	1.3.4	
GSX driver	R8A7796 GX6250 Device Driver for Linux	RCM3G001L4001ZDO	1.3.4	
GSX Offline Compiler	R8A7796 GX6250 GLSL Offline Compiler for Linux	RCM3G002L4001ZNI	1.3.4	
OMX	OMX Media Component Common Library for Linux	RTM0AC0000XCMCTL30SL40C	3.0.10	
OMX	OMX Media Component Video Decoder Common Library for Linux	RTM0AC0000XVCMND30SL40C	3.0.10	
OMX	OMX Media Component Video Encoder Common Library for Linux	RTM0AC0000XVCMNE30SL40C	3.0.10	
OMX	OMX Media Component H.263 Decoder Library for Linux	RTM0AC0000XV263D30SL40C	3.0.10	
OMX	OMX Media Component H.264 Decoder Library for Linux	RTM0AC0000XV264D30SL40C	3.0.10	
OMX	OMX Media Component H.265 Decoder Library for Linux	RTM0AC0000XV265D30SL40C	3.0.10	
OMX	OMX Media Component MPEG-2 Decoder Library for Linux	RTM0AC0000XVM2VD30SL40C	3.0.10	
OMX	OMX Media Component MPEG-4 Decoder Library for Linux	RTM0AC0000XVM4VD30SL40C	3.0.10	
OMX	OMX Media Component VC-1 Decoder Library for Linux	RTM0AC0000XVVC1D30SL40C	3.0.10	
OMX	OMX Media Component H.264 Encoder Library for Linux	RTM0AC0000XV264E30SL40C	3.0.10	
OMX	OMX Media Component DivX Decoder Library for Linux	RTM0AC0000XVDVXD30SL40C	3.0.10	

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe Referred S/W Packages

5. Revision Numbers of

Package Name (abbreviation)	Package Name	Package Id	Package Revision	
OMX	OMX Media Component RealVideo Encoder Library for Linux	RTM0AC0000XVRLVD30SL40C	3.0.10	
UVCS Driver	UVCS Driver for Linux	RCG3VUDRL4001ZDO	3.0.10	
OMX	OMX Media Component Audio Common Library for Linux	RTM0AC0000XACMND30SL40C	3.0.8	
OMX	OMX Media Component for AAC- LC Decoder Library for Linux	RTM0AC0000XAAACD30SL40C	3.0.8	
OMX	OMX Media Component for aacPlus V2 Decoder Library for Linux	RTM0AC0000XAAAPD30SL40C	3.0.8	
OMX	OMX Media Component for ALAC Decoder Library for Linux	RTM0AC0000XAALAD30SL40C	3.0.5	
OMX	OMX Media Component for Dolby(R) Digital Decoder Library for Linux	RTM0AC0000XADD5D30SL40C	3.0.3	
OMX	OMX Media Component for FLAC Decoder Library for Linux	RTM0AC0000XAFLAD30SL40C	3.0.5	
OMX	OMX Media Component for MP3 Decoder Library for Linux	RTM0AC0000XAMP3D30SL40C	3.0.8	
OMX	OMX Media Component for WMA Standard Decoder Library for Linux	RTM0AC0000XAWMAD30SL40C	3.0.8	
OMX	OMX Media Component for AAC- LC Encoder Library for Linux	RTM0AC0000XAAACE30SL40C	3.0.5	
AAC decoder	AAC-LC 2ch Decoder Middleware RTM0AC0000ADAACMZ1SL40C Library for Linux		3.0.8	
aacPlus V2 decoder	aacPlus V2 Decoder Middleware Library for Linux	RTM0AC0000ADAAPMZ1SL40C	2.0.8	
Dolby(R) Digital decoder	Dolby(R) Digital Decoder Middleware Library for Linux	RTM0AC0000ADDD5MZ1SL40C	2.0.4	
MP3 decoder	MP3 Decoder Middleware Library for Linux	RTM0AC0000ADMP3MZ1SL40C	2.0.8	
WMA standard decoder	WMA Standard Decoder Middleware Library for Linux	RTM0AC0000ADWMAMZ1SL40C	2.0.8	
AAC encoder	AAC-LC Encoder Middleware Library for Linux	RTM0AC0000AEAACMZ1SL40C	3.0.5	
CMS	Basic Color Management Middleware for Linux	RTM0AC0000JRCMBCV0SL40C	1.0.0	
CMS	CMM3 Backlight Control Middleware for Linux	RTM0AC0000JRCMBLC0SL40C	1.0.0	
CMS	VSP2 Dynamic Gamma Correction Middleware for Linux	RTM0AC0000JRCMDGV0SL40C	1.0.0	
ADSP	ADSP Interface for Linux	RCG3AHIFL4001ZDP	1.0.9	
ADSP	ADSP Driver for Linux	RCG3AHPDL4001ZDO	1.0.8	

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe Referred S/W Packages

5. Revision Numbers of

Package Name (abbreviation)	Package Name	Package Id	Package Revision
ADSP	ADSP Framework	RCG3AHFWN0101ZDP	1.0.8
ADSP	ADSP Reference Plugin	RCG3AHPLN0101ZNO	1.0.8

6. Commit ID of Renesas Yocto Recipe

Table 2: Commit ID of Renesas Yocto Recipe

Release	Repository	Branch	Commit ID
	git://github.com/renesas-rcar/meta-renesas.git	fido	5bea92a2b135cfe304605435a277b30a4e27788d
2.0.0	git://git.yoctoproject.org/poky	fido	cd2c9acdbd75c83790e8144d2a834f5b5de35df0b
	git://git.linaro.org/openembedded/meta-linaro.git	fido	7f630688d426831d195509843f9c8f282f459dd73
	git://github.com/renesas-rcar/meta-renesas.git	fido	0268245db91d3715b1816979e7063a94a2cae51b
2.1.0	git://git.yoctoproject.org/poky	fido	b50596d8f6e858e2e733f2d9913a19c6f3cd5863
	git://git.linaro.org/openembedded/meta-linaro.git	fido	3f1933242062d1cf473d20b86fa4582963ff9441
	git://github.com/renesas-rcar/meta-renesas.git	fido	d2a2b521ed1b807f82d861bd514c04468fd8bb42
2.2.0	git://git.yoctoproject.org/poky	fido	b74ea963cefffad9fbd91d4eb9b240f6a8c86cd0
	git://git.linaro.org/openembedded/meta-linaro.git	fido	3f1933242062d1cf473d20b86fa4582963ff9441
	git://github.com/renesas-rcar/meta-renesas.git	fido	63ccf5dcf40a15f039473f62e0fc0bdf36ad616f
2.3.0	git://git.yoctoproject.org/poky	fido	fa55b8e5050c6d7a47ef8e9bc213d0cc9471b43a
	git://git.linaro.org/openembedded/meta-linaro.git	fido	08a46787862966f2236c5a9b3eb4d4ec68263593
	git://github.com/renesas-rcar/meta-renesas.git	jethro	318c9b7daa44219a2f44e0966c17ae58266452c0
270	git://git.yoctoproject.org/poky	jethro	c8e5c38b8a36cbb45831fcd8469bd96068ae300c
2.7.0	git://git.linaro.org/openembedded/meta-linaro.git	jethro	acf4f1f701e07670ec88435897a74f88dbe8ba87
	git://git.openembedded.org/meta-openembedded	jethro	dc5634968b270dde250690609f0015f881db81f2
	git://github.com/renesas-rcar/meta-renesas.git	jethro	1d6ca1f7d9080c4807f60ed477be5311b107b16d
2.8.0	git://git.yoctoproject.org/poky	jethro	6dba9abd43f7584178de52b623c603a5d4fcec5c
	git://git.linaro.org/openembedded/meta-linaro.git	jethro	acf4f1f701e07670ec88435897a74f88dbe8ba87

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe 6. Commit ID of Renesas Yocto Recipe

Release	Repository		Commit ID
	git://git.openembedded.org/meta-openembedded	jethro	c305ac5d2f5285d5eec8952a4ca7f3b4f89aed96
	git://github.com/renesas-rcar/meta-renesas.git	jethro	20319d147591f9aaf2f32bf2d74abe188b538d61
200	git://git.yoctoproject.org/poky	jethro	65306b0bfc1afd0de9b1d470fd78c8c69f55f791
2.9.0	git://git.linaro.org/openembedded/meta-linaro.git	jethro	acf4f1f701e07670ec88435897a74f88dbe8ba87
	git://git.openembedded.org/meta-openembedded	jethro	cb7e68f2a39fa6f24add48fc7b8d38fb7291bb44
	git://github.com/renesas-rcar/meta-renesas.git	jethro	522efd09043aa8af1eec01af2b9e025df424d9a5
2.12.0	git://git.yoctoproject.org/poky	jethro	40376446904ae3529be41737fed9a0b650ed167d
2.12.0	git://git.linaro.org/openembedded/meta-linaro.git	jethro	9b1fd178309544dff1f7453e796a9437125bc0d9
	git://git.openembedded.org/meta-openembedded	jethro	8ab04afbffb4bc5184cfe0655049de6f44269990
	git://github.com/renesas-rcar/meta-renesas.git	krogoth	3613b2780a6b5d5d70ea6802be5060a8214cbdb5
2.16.0	git://git.yoctoproject.org/poky	krogoth	yocto-2.1.2 (cca8dd15c8096626052f6d8d25ff1e9a606104a3)
2.16.0	git://git.linaro.org/openembedded/meta-linaro.git	krogoth	2f51d38048599d9878f149d6d15539fb97603f8f
	git://git.openembedded.org/meta-openembedded	krogoth	55c8a76da5dc099a7bc3838495c672140cedb78e
	git://github.com/renesas-rcar/meta-renesas.git	krogoth	4979e05406c77524cf90b308ce4bf2a72032ee65
2.17.0	git://git.yoctoproject.org/poky	krogoth	yocto-2.1.2 (cca8dd15c8096626052f6d8d25ff1e9a606104a3)
2.17.0	git://git.linaro.org/openembedded/meta-linaro.git	krogoth	2f51d38048599d9878f149d6d15539fb97603f8f
	git://git.openembedded.org/meta-openembedded	krogoth	55c8a76da5dc099a7bc3838495c672140cedb78e
	git://github.com/renesas-rcar/meta-renesas.git	krogoth	95cb48ba09bc7e55fd549817e3e26723409e68d5
2.10.0	git://git.yoctoproject.org/poky	krogoth	yocto-2.1.2 (cca8dd15c8096626052f6d8d25ff1e9a606104a3)
2.19.0	git://git.linaro.org/openembedded/meta-linaro.git	krogoth	2f51d38048599d9878f149d6d15539fb97603f8f
	git://git.openembedded.org/meta-openembedded	krogoth	55c8a76da5dc099a7bc3838495c672140cedb78e

R-Car H3/M3 Series Release Note: Linux Interface Specification Yocto recipe 6. Commit ID of Renesas Yocto Recipe

Release	Repository	Branch	Commit ID
	git://github.com/renesas-rcar/meta-renesas.git	krogoth	52a5df36b4cd2ca0f5ec8eab9446f4f128ef727c
2.23.0	git://git.yoctoproject.org/poky	krogoth	yocto-2.1.2 (cca8dd15c8096626052f6d8d25ff1e9a606104a3)
2.23.0	git://git.linaro.org/openembedded/meta-linaro.git	krogoth	2f51d38048599d9878f149d6d15539fb97603f8f
	git://git.openembedded.org/meta-openembedded	krogoth	55c8a76da5dc099a7bc3838495c672140cedb78e

REVISION HISTORY		ORY	Linux Interface Specification Yocto recipe Release Note User's Manual: Software	
Rev. Date			Description	
Rev.	Date	Page Summary		
2.5.2	Jan 25 2016	2	2.2 updated version number	
2.5.2	Jan 23 2010	5	4.6 added history of v2.5.2	
		6	5 Table1 updated version number	
		7	6 Table2 added v2.5.2 commit id	
2.6.0	Feb 25 2016	2	2.2 updated version number	
2.0.0	1 05 20 20 10	5	4.7 added history of v2.6.0	
		6	5 Table1 updated version number	
		7	6 Table2 added v2.6.0 commit id	
2.7.0	Mar 25 2016	2	2.2 updated version number	
		6	4.8 added history of v2.7.0	
		7	5 Table1 updated version number	
		8	6 Table2 added v2.7.0 commit id	
2.8.0	Apr 25 2016	all	Added description for R-Car M3. For example, R-Car H3 -> R-Car H3/M3	
		2	2.2 updated version number	
		6	4.9 added history of v2.8.0	
		7-8	5 Table1 updated version number and add new MMP	
		9	6 Table2 added v2.8.0 commit id	
2.9.0	May 25 2016 2		2.2 updated version number	
		7	4.10 added history of v2.9.0	
		8-9	5 Table1 updated version number and add new MMP	
		10-11	6 Table2 added v2.9.0 commit id	
2.10.0	Jun 27 2016	2	2.2 updated version number	
		7	4.11 added history of v2.10.0	
		8-9	5 Table1 updated version number and add new MMP	
		10-11	6 Table2 added v2.10.0 commit id	
2.11.0	Jul 25 2016	2	2.2 updated version number	
		7	4.12 added history of v2.11.0	
		9-11	5 Table1 updated version number and add new MMP	
		12-13	6 Table2 added v2.11.0 commit id	
2.12.0	Aug 25 2016	2	2.2 updated version number	
		7	4.13 added history of v2.12.0	
		9-11	5 Table1 updated version number and add new MMP	
		12-13	6 Table2 added v2.12.0 commit id	
2.15.0	Dec 07 2016	2	2.2 updated version number	
		8	4.14 added history of v2.15.0	
		9-11	5 Table1 updated version number	
		13	6 Table2 added v2.15.0 commit id	
2.16.0	Jan 27 2017	2	2.2 updated version number	
		3	3 fixed typo	
		8-9	4.15 added history of v2.16.0	
		10-11	5 Table1 updated version number	

		10.40	0. Table 0. add at 0.0 40.0 a arrow 2 id
		12-13	6 Table2 added v2.16.0 commit id
2.17.0	Mar 30 2017	2	2.2 updated version number
		8	4.14 Changed address format from H'xxxx to 0xxxxx
		9	4.15 Changed address format from H'xxxx to 0xxxxx
			4.16 added history of v2.17.0
		10-11	5 Table1 updated version number
		13	6 Table2 added v2.17.0 commit id
2.19.0	Apr 26 2017	-	Unified the Chip version "Ver/ES/WS" to "Ver."
		-	Unified the Yocto recipe version from "Ver" to "v"
		-	Changed "U-boot" to "U-Boot"
		2	2.2 updated version number
		10	4.17 added history of v2.19.0
		12	5 Table1 updated version number
		14	6 Table2 added v2.19.0 commit id
2.21.0	Jun 28 2017	2	2.2 updated version number
		10	4.14 added history of v2.21.0
		11-15	5 Table1 updated version number
		15	6 Table2 added v2.21.0 commit id
2.23.0	Aug 29 2017	-	Add "CONFIDENTIAL" mark
		8	Change "R-Car Gen3" to "R-Car Series, 3rd Generation"
		2	2.2 updated version number
		11	4.19 added history of v2.23.0
		12-14	5 Table1 updated version number
		17	6 Table2 added v2.23.0 commit id

Linux Interface Specification Yocto recipe

Release Note: Software

Publication Date: Rev.2.23.0 Aug. 29, 2017

Published by: Renesas Electronics Corporation



SALES OFFICES

Renesas Electronics Corporation

http://www.renesas.com

Refer to "http://www.renesas.com/" for the latest and detailed information.

Renesas Electronics America Inc. 2801 Scott Boulevard Santa Clara, CA 95050-2549, U.S.A. Tel: +1-408-588-6000, Fax: +1-408-588-6130

Renesas Electronics Canada Limited 9251 Yonge Street, Suite 8309 Richmond Hill, Ontario Canada L4C 9T3 Tel: +1-905-237-2004

Renesas Electronics Europe Limited
Dukes Meadow, Millboard Road, Bourne End, Buckinghamshire, SL8 5FH, U.K
Tel: +44-1628-585-100, Fax: +44-1628-585-900

Renesas Electronics Europe GmbH

Arcadiastrasse 10, 40472 Düsseldorf, Germany Tel: +49-211-6503-0, Fax: +49-211-6503-1327

Renesas Electronics (China) Co., Ltd. Room 1709, Quantum Plaza, No.27 ZhiChunLu Haidian District, Beijing 100191, P.R.China Tel: +86-10-8235-1155, Fax: +86-10-8235-7679

Renesas Electronics (Shanghai) Co., Ltd.
Unit 301, Tower A, Central Towers, 555 Langao Road, Putuo District, Shanghai, P. R. China 200333 Tel: +86-21-2226-0888, Fax: +86-21-2226-0999

Renesas Electronics Hong Kong Limited
Unit 1601-1611, 16/F., Tower 2, Grand Century Place, 193 Prince Edward Road West, Mongkok, Kowloon, Hong Kong Tel: +852-2265-6688, Fax: +852 2886-9022

Renesas Electronics Taiwan Co., Ltd. 13F, No. 363, Fu Shing North Road, Taipei 10543, Taiwan Tel: +886-2-8175-9600, Fax: +886 2-8175-9670

Renesas Electronics Singapore Pte. Ltd.
80 Bendemeer Road, Unit #06-02 Hyflux Innovation Centre, Singapore 339949
Tel: +65-6213-0200, Fax: +65-6213-0300

Renesas Electronics Malaysia Sdn.Bhd.
Unit 1207, Block B, Menara Amcorp, Amcorp Trade Centre, No. 18, Jln Persiaran Barat, 46050 Petaling Jaya, Selangor Darul Ehsan, Malaysia Tel: +60-3-7955-9390, Fax: +60-3-7955-9510

Renesas Electronics India Pvt. Ltd.
No.777C, 100 Feet Road, HAL II Stage, Indiranagar, Bangalore, India Tel: +91-80-67208700, Fax: +91-80-67208777

Renesas Electronics Korea Co., Ltd. 12F., 234 Teheran-ro, Gangnam-Gu, Seoul, 135-080, Korea Tel: +82-2-558-3737, Fax: +82-2-558-5141

© 2017 Renesas Electronics Corporation. All rights reserved.



営業お問合せ窓口

http://www.renesas.com

営業お問合せ窓口の住所は変更になることがあります。最新情報につきましては、弊社ホームページをご覧ください。

ルネサス エレクトロニクス株式会社 〒135-0061 東京都江東区豊洲3-2-24(豊洲フォレシア)

接合お問合せ窓口:https://www.renesas.com/contact/		

Linux Interface Specification Yocto recipe Release Note

